

Additional Manhole Repairs identified by the Utility Division

Address	Street	Date Repaired	Original Install Date	Age	Scheduled Inspection	
780	S. MacArthur	2015	2004	11	2015	Red=Immediate Repairs Needed
777	S. MacArthur	2015	1988	27	2015	Yellow= Needs Repair Soon
780	S. MacArthur	2015	2004	11	2015	Green= Repairs Made
360	N. Coppel Rd.	2015	1978	37	2015	
601	Canyon	2015	1981	34	2015	
620	N. Coppel Rd.	2015	1997	18	2015	
234	E. Parkway Blvd	2015	1976	39	2015	
364	N. Denton Tap Rd.	2015	1978	37	2015	
????	Andy Brown East (Natural Area)	2015	7/31/1976	40	2016	Repairs Made in December 2016
810	Denton Tap Rd.		10/31/1978	38	2017	
628	East Bethel Rd.				2017	
538	Waterview		7/30/1996	20	2017	
337	Waterview		8/1/1988	29	2017	
457	Phillips		7/31/1976	40	2017	
441	Parkway		4/30/1983	34	2017	
133	Cottonwood		7/31/1976	40	2017	
149	Cottonwood		7/31/2017	40	2017	
780	S. MacArthur		12/15/2004	13	2016	
780	S. MacArthur		12/15/2004	13	2016	
780	S. MacArthur		12/15/2004	13	2016	
618	Oak Grove Ln.		10/31/1978	39	2015	
618	Oak Grove Ln.		10/31/1978	39	2015	
615	Oak Grove Ln.		10/31/1978	39	2015	